

DON'T SAY IT - WRITE IT

To _____

Date 4-3-80

From _____


DRY CYCLE TEST : SAFETY SNAP WASHER CLIP
WITH ~~ONE~~ ^{TWO} DETENTS ON SPRING

NUMBER OF CYCLES 10,000

SPRING # 3

1000 - OK
2000 - OK
3000 - OK
4000 - OK
5000 - OK
6000 - OK
7000 - OK
8000 - OK
9000 - OK
10000 - OK

START
POSITION



Position not
CHANGED

SOME SPRING TENSION
LOST.

CHECK BY: _____

Angelo

DON'T SAY IT — WRITE IT

Date 4-3-80

To _____

From _____


DRY CYCLE TEST : SAFETY SNAP WASHER CLIP
WITH ~~ONE~~ TWO DETENTS ON SPRING

NUMBER OF CYCLES 6428

1000 - OK.
2000 - OK
3000 - OK
5000 - O.K. Set
6000 - OK

6428 - spring set

CAUSING NO SPRING PRESSURE
ON SAFETY DETENT BALL -
very sloppy safety



CHECK BY: Sal R. Angelo

DON'T SAY IT — WRITE IT

To _____

Date


4-3-80

From _____

DRY CYCLE TEST : SAFETY SNAP WASHER CLIP
WITH ONE DETENT ON SPRING

NUMBER OF CYCLES ① TOTAL 5000

rotation started
at 1500 cycles

CHECK BY: Sal + Angelo

DON'T SAY IT — WRITE IT

To _____


Date

4-3-53

From _____

DRY CYCLE TEST : SAFETY SNAP WASHER CLIP
WITH ONE DETENT ON SPRINGNUMBER OF CYCLES 5000

1000 - OK
2000 - OK
3000 - moved slightly
4000 - moved & clatter
5000 - moved to
3/4 across.

CHECK BY: SAL 'Angels'


G-48

DON'T SAY IT — WRITE IT


To _____

Date _____

From _____



M/700 Safety Lever
with view hole
26,428 cy. 8-80



Assembled Component
M/700 Safety Lever
Dual detent spring