

SEQUENCE OF OPERATIONS

OP. No.	OPERATION	DEPT.	OP. No.	OPERATION	DEPT.
	DRAW THE FOLLOWING PARTS TO MAKE A FIRING PIN ASSEMBLY				
	Bolt Plug		15676		
	Firing Pin		15410		
	Firing Pin Cross Pin		17022		
	Firing Pin Head		23321		
	Main Spring		15411		
100	Assemble Firing Pin, Main Spring, Bolt Plug, and Firing Pin Head.	02			
110	Rethread Bolt Plug.	61			
120	Wash To Remove Chips, TO FINAL ASSEMBLY - CRIB #29	61			
DATES AND REASONS FOR REVISIONS			DATES AND REASONS FOR REVISIONS		
9/29/80 - Retyped & revised for MRP - ERW - 279138					
2/10/81 - Added oper. #110&120 - DRL - 280157					
5/8/81 - Chg. Dept. # - JRH - 280469					
MODEL Moh 600, XP-100		PART NAME Firing Pin Assembly		PAGE 1	OF 1
		GA. OR CAL.			
		PART No.	28600		

RD-8480

804-0408