

A

L

E

*Quality*

May 18, 1954.

TO: R.J. HACDAN (S)

FROM: QUALITY CONTROL DEPARTMENT

SUBJECT: M/72-722 TRIGGER PULL

Referring to S. N. Alvis' letter of 3/22/54 to R. J. Hacdan on the above subject -

The attached distribution indicates that the subject characteristic is not very well controlled in our finished guns.

If feasible, from the time and cost point-of-view, the picture could be improved by instructing the Assemblers making the Trigger Pull adjustment to work to the mean of the spec. It is suggested that the distribution would be a helpful part of any such instructions.

A corollary problem of variable Trigger Pull was evidenced on four to six of the Fifty-eight (58) guns.

MAB/MAB

QUALITY CONTROL DEPARTMENT  
A. D. Gordon, Supervisor  
BY V. S. Bryant  
V. S. Bryant

C  
H

PLAINTIFF'S  
EXHIBIT

3117

AL 0023720

1 of 1