

SEQUENCE OF OPERATIONS

OP. No.	OPERATION	DEPT.	OP. No.	OPERATION	DEPT.
			80	Assemble Front Sight Base to Barrel with Front Sight Base Screws.	61
20	Assemble Rear Sight Assembly.	61			
30	Remove burr from Ejector hole at face of Bolt.	61			
40	Fit and head Bolt Assembly to Barrel Assembly.	61			
50	Fit and head Bolt Assembly to Barrel Assembly (GMM)	61			
65	Make chamber cast.	61			
70	Ream Ejector hole.	61			

DATES AND REASONS FOR REVISIONS		DATES AND REASONS FOR REVISIONS	
3/4/78 - Retyped & filed with process no. 276772		10/31/78 - Rev. and re-numbered Op. 5-18 WW	
3/4/78 - Chg. dept. 41 to 61 - Hardy - 276772		7/7/83 - Obs. Op. 17 & chg. page # - RLS - 283006	
5/23/78 - Obs. op. 16 - combined with op. 15 - MH-276920			
MODEL	Mohawk 600	PART NAME	Final Assembly
	GA. OR CAL.		
	PART NO.		

RD-8480

CONFIDENTIAL-SUBJECT TO PROTECTIVE ORDER

KINZER V. REMINGTON
BARBER - PRESALE R 0114044
R2515032