

Rev. 2-19-61

P.I. NO GUN EXAMINATION REPORT NUMBER: 500 MODEL: 700 BDL
 GENERAL CONDITION: GOOD R #: 19506
 OUTSIDE WORK: SCOPE BASE ADDED DATE: 7-30-81
 FROM: H.G. BENTLIN
2646 JACKSON Pk.
FALLS CHURCH VA
 FIRED AMMO TYPE: NOT KNOWN GUN #: 223209
 & CONDITION: _____ CODE: ON-7-66
 PROCP: (REP) INSP.: 9 TEST: 87 GA./CAL.: 243
 HEADING: OK CHECKED BY: M-HARDY
 BREACH OPENING: OK APPROVED: GA 6/1/81
 RECOIL SHOULDERS: OK APPROVED: PG 2 6/1/81
 CHAMBER: OK APPROVED: FM 6/1/81
 TEST: _____ APPROVED: 2-2-81
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: 6-1-81

OLD STYLE FIRE CONTROL. SLIGHT DENTS IN WOOD

COMPLAINT: FIRE WHEN SAFE IS RELEASED, 47 TIMES

INCIDENT: _____

COMMENTS:

See - safety cam sticks in downward position,
because of accumulation of dirt & oil. Clean & return
to customer. Clean Bolt & Firing Pin Hammer, and has
on it as it also.

Send new instruction manual to customer.