

Rev. 2-15-61

P.I. NO GUN EXAMINATION REPORT NUMBER: 530MODEL: 700 BDLGENERAL CONDITION: FAIRR #: 24180OUTSIDE WORK: S/REMOVED SCOPE MOUNTS ADDEDDATE: 10-9-81TRIG + CONNECTOR REMOVED AS ISFROM: BILLY M. SWEETFIRED AMMO TYPE: NOT KNOWNRT. 22 BOX 186AALLEN TON TEN.

& CONDITION:

GUN #: A1376164PROOF: 1 INSP.: 123 TEST: 64CODE: RI-11-76READING: OKGA./CAL.: 1, M4 REMBREACH OPENING: OKCHECKED BY: M-HA 904RECOIL SHOULDERS: OKAPPROVED: 9/28/10/21/81CHAMBER: OKAPPROVED: 10/10/12TEST: CHECKED FIRE PIN PROTRUSION, OKAPPROVED: 10/22-81

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: 10/22-81TRIG. CONNECTOR BROKENCOMPLAINT: FIRE WHEN TAKEN OFF SAFETY

INCIDENT:

COMMENTS:

Please replace fire control - no chance50+