

Rev. 2-15-61

P.I. 1/57 GUN EXAMINATION REPORT NUMBER: 528 MODEL: 700
 GENERAL CONDITION: FAIR R #: 23771
 OUTSIDE WORK: SIGHT REMOVED, RECOIL PAD AND DATE: 10-2-81
SWIVEL STUDS ADDED FROM: CAL REDDICK
920 W. LAKE CANNON DR
WINTER HAVEN FLA
 FIRED AMMO TYPE: NOT KNOWN GUN #: 359092
 & CONDITION: _____ CODE: OR-7-68
 PROCP: PER INSP.: 9 TEST: 55 GA./CAL.: 3006
 HEADING: OK CHECKED BY: M. HARDY
 BREACH OPENING: OK APPROVED: GAH 10/22/81
 RECOIL SHOULDERS: OK APPROVED: PER 10/22/81
 CHAMBER: OK APPROVED: P. H. 10/22/81
 TEST: _____ APPROVED: JWB 10/22-81
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: GAH 10/22/81
BOLT RUSTY BRIGHT METAL ON BAL.
MARS ON STOCK, 2 1/2 LB. TRIG PULL

COMPLAINT: FIRE WHEN SAFETY IS RELEASED

INCIDENT: _____

COMMENTS: Unable to duplicate customer complaint.

Gun passes field test, 100" vertical zero lift -
1017 Trigger connector engagement.

Trigger adjustment screws adjusted outside factory,
as evidenced by red glue on these screws. Trigger pull
2 1/2# - Rem Scales 3# to 5#

Control set follow down by slamming butt.