

11-18-83

DEAR JIM

THIS IS THE RIFEL WE TALKED ABOUT
TODAY ON THE TELEPHONE.

ON TWO OCCASIONS, 11-15-82 AND
11-15-83, THIS RIFEL HAS FAILED TO
OPERATE PROPERLY. BOTH TIMES I
WAS AIMING AT A DEER. THE SAFETY
WAS OFF AND I COULD NOT PULL THE
TRIGGER. THERE WAS NO CLICK AND
NO TRIGGER MOVEMENT. BOTH TIMES
WHEN I LOWERED THE RIFEL TO SEE
WHAT WAS WRONG IT FIRED WITHOUT
TOUCHING THE TRIGGER.

YOU WILL NOTICE THE CHECKERING
IS ALMOST GONE DUE TO REFINISHING
THE WOOD. IF IT IS POSSIBLE TO
RECHECKER THE WOOD SEND ME THE
COST AND I WILL MAIL A CHECK TO
COVER THE WORK. DON'T WORRY ABOUT
THE FINISH ON THE WOOD AFTER
CHECKERING (IF POSSIBLE) I WILL TAKE
CARE OF THAT.

YOUR FRIENDLY COURTEOUS ATTITUDE
DURING OUR TELEPHONE CONVERSATION

WAS GREATLY APPRECIATED.

Sincerely,

Lee Conroy