

NEW BAR MEETING.

10-31-88

- LITIGATION - NO/700 SAME F. N. BAR ROUND BOTTOM
- MAGAZINE DISCONNECT -
- 700 FUNCTIONAL IMPROVEMENT PROGRAM
 - F. CONTROL - NEW (LOOK AT N' FEEL NOW) ^{3-5TH} ADJUST
 - MAG. BOX DETACHABLE
 - BODING DENSE
 - BOLT LOCK ^{LOOK AT V} COLT - SAUER PATENT RARS OUT 89, ^{BUTTON ON BOLT HANDLE}

DR. BEN COMMINGS - AMERPEEN - HUMAN FACTORS

- ? MAG. LATCH AT FRONT PART OF TRIGGER GUARD
- BOLT LOCK

F. CONTROL 700 - LITIGATION TOO, TOO TIGHT & TOO
CLOSE OUTSIDE OF F. CONTROL TO PREVENT
DEBRIS FROM ENTERING, + PROVIDE INTERNAL
CLEARANCE FOR PARTS BY RELIEVING PARTS

- REBALANCE TRIGGER

788 POWDERMETAL TRIGGER - SEAR LOOK AT WEAR

LOOK AT WIN M/54 ONE PIECE SEAR

ALSO OLD 2 PC M/721 SEAR (STAMPING)


COMPARISON TRIGGER BLOCK - SEAR BLOCK FEATURE GOOD
ON NEW BAR

LOOK AT RUGER ONE PC CONNECTOR


- CONNECTOR -

TRIGGER SPRING WEIGHT IS TOO HIGH - HUTTON SAYS
NEED A LONGER RATE RATIO BETWEEN FULL ENGAGEMENT
TO JUST READY TO RELEASE TO INSURE RETURN
OF TRIGGER TO FULL ENGAGEMENT WHEN RELEASED

- TRIGGER PLATE TWO PIECE ASSY,
MAYBE MIM



HAVE SEAR DOWN + MAKE ON OWN PIVOT



NEW DATE

- SAFETY - MAKE DETENT POSITIVE ORK - ON
3 # MIN FORCE REQ'D.

SWS - 2 - 10 #

GET RWD OR BALL



LOCATION OF SAFETY BUTTON IS GOOD AESTHETICALLY +
HUMAN ENG. WISE

• NO MAGAZINE BOX DISCONNECT WANTED PETZ HUTTON

• SAUER - LOADED CHAMBER INDICATOR LOOK AT

LEGAL WANTS ONE

- EJECTOR PLUNGER ^{LOADED CHAMBER} INDICATOR OPERATES OFF OF

• LOOK AT AUG MOULDED PLASTIC FIRE CONTROL

• READING - FOCUS PANEL DATA

OTTESON - DETAILS RETAINED BY ATTORNEY

• CLIP - COLD TESTING - ~~FOR~~ REMINGTON

CONV SPEC, F. CONTROL TESTING,

HUTCHIN - TO CHECK W/ ABERDEEN

- H.P. WHITE