

DATE - 2-7-00 THRU 2-11-00
SHOOTER - JESSE

PROJECT# 241095
TLW 9256C

MODEL 710 FUNCTION / ENDURANCE TEST.

GUN	AMMO	ROUNDS	MALFUNCTIONS	
			STEM LOW	MISFIRE
XC 1071	R30064	300	31	
	R30061	100	1	1
	R3006B	400	7	1
	R30065	700	6	1
	R30063	500	0	0
	TOTAL	2000	45	3

NOTE: HEAD SPACE AT START OF TEST +.003

NOTE: HEAD SPACE AT END OF TEST +.004

NOTE: GUN FUNCTION WAS SMOOTH EXCEPT FOR AMMO - R30064

GUN	AMMO	ROUNDS	MALFUNCTIONS	
			STEM LOW	MISFIRE
XC 1075	R30064	340	15	
	R30061	580		1
	R3006B	480	9	
	R30065	200		
	R30063	400		1
	TOTAL	2000	24	2

NOTE: (528 RDS.) BROKEN FIRING PIN HEAD. REPLACED WITH KNOWN OTHER PROBLEMS.

HEAD SPACE AT START OF TEST +.003

HEAD SPACE AT END OF TEST +.005

NOTE: GUN FUNCTION WAS SMOOTH EXCEPT FOR AMMO - R30064

ET36119