

DESIGN CHANGE REQUEST (DCR)
PARTS LIST CHANGE NOTICE (PLCN)

DCR # 03309Sheet 1 of 1~~PARTS LIST TRANSMITTAL~~

Requested by <u>PEIC</u>	Changed by <u>HAUER</u>	Date <u>1-9-73</u>
Originating Date <u>12/14/72</u>	Transmittal Date <u>4-3-73</u>	

~~TRANSMITTAL of DRAWINGS / PARTS LIST~~

Model	Part Name/List	Drawing No.	Part No.
1100	RETURN PLUNGER RETAINING PIN	A-32165	32165
788	EJECTOR PIN	A-17676W	17676
1100	ACTION BAR ASS'Y, 12-16-20 GH	C-26085	26086
1100	ACTION BAR ASS'Y, 28-40-20 L.W.	C-30010	30010-11

Dwg. No.	Rev. No.	Design Change
A-32165	5	OBSOLETE
A-17676W	31	ADD USE FOR M/1100 RETURN PLUNGER RETAINING PIN
C-26085	27	RETURN PLUNGER RET. PIN WAS A-32165 NO. 4-17-72
C-30010	18	" " " " WAS A-32165 NO. 4-17-72

Reason for Change: PIN A-17676-W IS LESS EXPENSIVE, EASIER TO ASSEMBLE AND DISASSEMBLE, AND CAUSES LESS BINDING OF THE RETURN PLUNGER. PRODUCTION HAS BEEN USING THIS PIN FOR ABOUT 6 MOS.

Disposition of Parts On Hand (check below)

☒ Scrap ☐ Alter ☐ Use Inventory

(PLCN) Use form below if part number is changed/add-used, or superseded

	Dwg. No.	Part No.	Part Name	Qty.	Assem. No.
Current Listing	A-32165	-	RETURN PLUNGER RETAINING PIN		
New Listing	A-17676W	-	RETURN PLUNGER RETAINING PIN		
Current Listing					
New Listing					
Current Listing					
New Listing					

Note: Please mark your Parts List to agree.

☐ Superseded Part is Obsolete (check disposition below)

☐ Use up ☐ Scrap ☐ Service Repair ☐ Other Model Use

☐ New Part is: ☐ Steel ☒ Powder Metal ☐ Assembly ☐ Wood ☐ Purchased ☐ Other