							DCR #10615				
	DESIGN CH		Sheet of								
_	PARTS LIS	T CHA	IGE NOTICE :: (PŁCN)					 -		
	PARTS LIST TRANSMITTAL GORSKI					Request	ed By	Cha	nged By	Date	
ı						P.E.=	€C.	F.A	NARTIN	BFEB 78	
						Originating Date			Transmittal Date		
	TRANSMIT	TRANSMITTAL of DRAWINGS - PARTS LIST Model Part Name / List					·			2-14-78	
	Model						Drawing No		Part No.		
	XP -100	(P-100 TRIGGER						45	7 .	~	
	<u> </u>										
					<u> </u>	•					
	Dwg. No.	Rev. No. Design Change									
C-15457 5 ADDED .OG RADIUS											
		ļ	·							·	
		-									
Reason for Change: FOR EASE IN MANUFACTURING B									5 P.I.		
	Reason for Change: FOR EASE IN MANUFACTURING BY POWDER METAL										
Disposition of Parts on Hand (check below) () Scrap () Alter (Use Inventory (PLCN) Use form below if part number is changed / add – used, or superseded.											
									· · · · · · · · · · · · · · · · · · ·		
	Drawing No. Part No. Current Listing New Listing					Part Name					
	Current Listing										
	New Listing							·	·		
	NOTE: Please mark your Parts List to agree ()										
() Superseded	Superseded Part is Obsolete (check disposition below)									
•	() Use Up () Scrap () Service Repair () Other Model Use										
(New Part is: () Steel () Powder Metal () Assembly () Wood () Purchased () Other									
	APPROVED:	APPROVED: 20 10 10 10 13/13/12 CS 2/14/18									
	12										

BARBER - PRESALE R 0121147