

Curt Corp

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700

GENERAL CONDITION: FAIR R #: -

OUTSIDE WORK: RECEIVER RE-COLORED, DATE: 1-22-73

NEW BARREL FITTED, SPECIAL SLINGS, FROM: _____

FIRE AMMO TYPE: -

& CONDITION: DIATHALON GUN GUN #: 6403732

PROOF: NO MARKING TEST: - CODE: NO MARKING

HEADING: MAX. GA./CAL.: 22 P

BREECH OPENING: - CHECKED BY: C. PROSSER

RECOIL SHOULDERS: EXCESSIVE RADIUS - REAR APPROVED: _____

CHAMBER: O.K. APPROVED: _____

TEST: 20 ROUNDS - AFTER FITTING NEW BOLT APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

OLD STYLE SAFETY - COCKING CAM DAMAGED
BY SAFETY. HEADING MAX DUE TO BEARING ON
EXCESSIVE RADIUS AT REAR OF RECOIL SHOULDERS.

COMPLAINT: _____

INCIDENT: _____

PLAINTIFF'S
EXHIBIT

3180

COMMENTS: THE BEARING ON THE RADIUS AT REAR OF RECOIL
SHOULDERS CAUSED HEAVY BOLT LIFT, FURTHER
INTERFERENCE BY CLOSING AND LOCKING THE
BOLT WITH THE SAFETY "ON" COULD CAUSE A
JAM AND DAMAGE TO THE COCKING CAM.