

I. NO GUN EXAMINATION REPORT NUMBER: _____GENERAL CONDITION: GOODOUTSIDE WORK: SCOPE MOUNTEDFIRED AMMO TYPE: -

& CONDITION: _____

PROOF: R.E.P. INSP. U TEST: ?HEADING: O.K.BRECH OPENING: -RECOIL SHOULDERS: O.K.CHAMBER: O.K.

TEST: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

Cast. Compl.MODEL: 700ADLR #: 000972DATE: 1-5-73FROM: COOPER'S
SPORTING GROUPSMANFIELD, PA.GUN #: 300043CODE: NP = 8/67GA./CAL.: 270WIN.CHECKED BY: C. PROSSER

APPROVED: _____

APPROVED: _____

APPROVED: _____

APPROVED: _____

BOLT HANDLE BROKEN OFF. TRIGGER BINDING -
HEAVY LUBRICANT - CONNECTOR STUCK TO
TRIGGER. CORNER OF SEAR BROKEN DOWN.

COMPLAINT: FIRES WHEN SAFETY IS TAKEN OFF.INCIDENT: FOLLOW DOWNPLAINTIFF'S
EXHIBIT3181

COMMENTS: THE TRIGGER BINDING AS A RESULT OF THE
DRIED OUT LUBRICANT FAILED TO RETRACT,
REMAINING IN FIRED POSITION, CAUSED THE
FOLLOW DOWN.