

Model 710

Discussion Thread

Response (Chris)
Dear Mr. McCarty,

10/1/2004 3:46:59 PM

Thank you for your inquiry. We changed the bolt stop on the Model 710 in the first year for added strength. Current models do not have a problem with this. If you have this problem, we recommend taking/shipping the firearm to one of the following Remington Premier Repair Centers for inspection.

Send to J & G if you live in the following states: CA, NV, UT, AZ
J & G Gunsmithing
625 Vernon St
Roseville, CA 95678
916-786-9200

Send to Allison & Carey if you live in the following states: OR, WA, ID, MT, AK
Allison & Carey Gun Works, Inc.
17311 SE Stark
Portland, OR 97233
Phone: 503-256-5166

Send to Sportsman's Haven if you live in the following states: OH, PA, WV, VA, VT, NH, MD, DE
Sportsman's Haven, Inc.
14695 East Pike Rd.
Cambridge, OH 43725
Phone: 740-432-7243
Fax: 740-432-3204

Send to Mann & Son if you live in the following states: IL, IN, MS, AR, WI
Mann & Son Sporting Goods
515 W Water St.
Pinckneyville, IL 62274
Phone: 618-357-2911
Fax: 618-357-3658

Send to Ahlman's if you live in the following states: MN, IA, MO, KS, IN, SD, ND, WY, NE
Ahlman's, Inc.
9525 W. 230th Street
Morristown, MN 55052
Phone: 507-685-4244
Fax: 507-685-4280
<http://www.ahlmans.com/>

Send to Sports World if you live in the following states: OK, TX, NM, CO, LA
Sports World, Inc.
5800 S. Lewis Ave. Suite 154
Tulsa, OK 74105
Phone: 918-742-4027
Fax: 918-72-3981

Send to Paducah if you live in the following states: KY, TN, NC, SC, GA, AL, FL
Paducah Shooters Supply, Inc.
3919 Cairo St.
Paducah, KY 42001
Phone: 270-442-3242