

222	MODIFY TUBE CAPACITY TO ACCEPT 10 ROUNDS
113	MUZZLE DAMAGE
231	NIPPLE NOT TO FACTORY SPECIFICATIONS
114	NO CORRESPONDENCE
115	NO FAULT FOUND AT BENCH
216	OPENS WHEN FIRED
217	OVER LOCKED
116	PACKING ERROR
220	PISTON/PISTON SEAL INCORRECTLY INSTALLED
117	POOR FINISH - BARREL
118	POOR FINISH - FORE END
119	POOR FINISH - RECEIVER OR FRAME
120	POOR FINISH - STOCK
143	POOR RECOIL PAD TO STOCK FIT
218	PREPLAY ON SEAR NOT TO FACTORY SPECIFICATIONS
234	RECEIVER BROKEN AT BARREL CLAMP
236	RECEIVER BROKEN AT BARREL CLAMP
221	RECEIVER FEED CUTS ARE ROUGH
232	RECEIVER INSERT IS MISSING
121	RECEIVER IS MISCUT
153	RECEIVER PLUG SCREWS BROKEN
154	RECEIVER SCOPE MOUNT HOLES OFF CENTER
239	REPLACED TRIGGER ASSM (700 ONLY)
233	RESIZE BORE
235	RESIZE BORE
241	RETURN GUN TO FACTORY
176	RETURNED FOR RECALL/UPDATE
165	RIB DOESN'T ALIGN WITH RECEIVER
166	RIB IS DAMAGED
167	RIB LANDS ARE LOOSE
167	RIB SWEEPS TO THE LEFT
169	RIB SWEEPS TO THE RIGHT
139	RIFLING ROUGH/MISCUT/DAMAGED
144	ROLL MARKING VISIBLE INSIDE BORE
122	RUSTED COMPONENT
123	SAFETY CONCERN, EXAMINED BY PRODUCT SERVICE
246	SAFETY SPRING INSPECTION/REPLACEMENT (710)
170	SCOPE MOUNT THREADS UPSET IN RECEIVER
243	SEE CUSTOMERS LETTER FOR MORE INFO
124	SIGHTS OFF CENTER
125	STOCK CRACKED
126	STOCK MARRED
177	STOCK NOT BEDDED PROPERLY
178	TRIGGER ADJ SCREWS RESET, CANNOT READJUST
135	TRIGGER CONNECTOR BINDS
127	TRIGGER PULL IS OUT OF FACTORY SPECS
242	UPDATE (710 BACKERS AND BOLT STOP)
244	UPDATE BOLT STOP
138	WILL NOT FEED PROPERLY