ACCURACY BALANCE OF FIREARM IS NEEDED TO PERFORM PROPER REPAIR BUTT PLATE / RECOIL PAD IS BROKEN CHAMBER ROUGH / RINGS / TEARS / TIGHT CONSIGNED GUN COULD NOT DUPLICATE CUSTOMERS COMPLAINT CREDIT RETURN DAMAGE APPEARS TO HAVE OCCURRED IN TRANSIT® DAMAGES CASES, BULLETS, OR SHELLS FAILS TO FIRE FINISH IS DAMAGED ON TRIGGER GUARD/PLATE HEADSPACE IS EXCESSIVE MUZZLE DAMAGE NO CORRESPONDENCE NO FAULT FOUND AT BENCH PACKING ERROR POOR FINISH - BARREL POOR FINISH - FORE END POOR FINISH - RECEIVER (OR FRAME) POOR FINISH - STOCK RECEIVER IS MISCUT RUSTED COMPONENT FORWARD TO PRODUCT SERVICE FOR INSPECTION SIGHTS OFF CENTER STOCK CRACKED STOCK MARRED TRIGGER PULL IS OUT OF FACTORY SPECS CHAMBER DIRTY / RUSTY FAILS TO EXTRACT HEADSPACE AT MINIMUM LIGHT OR NO INDENT FROM FIRING網網 BLUING SALTS BLEEDING FROM METAL EXTRACTOR MISSING FAULTY MAGAZINE TRIGGER CONNECTOR BINDS EXTRACTOR IS BROKEN FAILS TO EJECT WILL NOT FEED PROPERLY RIFLING ROUGH / MISCUT / DAMAGED ACTION IS DIFFIONLY TO OPEN EXTRACTOR IS CATCHING ON SHELL HEAD MAGAZINE DIFFICULT TO LOAD POOR RECOIL PAD TO STOCK FIT ROLL MARKING VISIBLE INSIDE BORE BOLT HANDLE FELL OFF, BOLT IS BROKEN FORE END CRACKED FORE END FIT IS TOO TIGHT FORE END FIT IS TOO LOOSE FORE END MARRED GRIP CAP IS DAMAGED ACTION BAR IS BROKEN

Subject to Protective Order Williams v. Remington