

NO GUN EXAMINATION REPORT NUMBER: \_\_\_\_\_ MODEL: 700 BDL  
 GENERAL CONDITION: NEW R #: 027181  
 OUTSIDE WORK: SCOPE MOUNTED DATE: 12-18-72  
 FROM: BRUCE WIGGINS  
 SPORTS SHOP  
 FIRED AMMO TYPE: \_\_\_\_\_ BEAUMONT, TEXAS  
 & CONDITION: \_\_\_\_\_ GUN #: 6418163  
 PROOF: R.E.P. INSP.: 73 TEST: 55 CODE: AU = 3/71  
 HEADING: O.K. GA./CAL.: 17 REM.  
 BREACH OPENING: - CHECKED BY: C. PROSSER  
 RECOIL SHOULDERS: O.K. APPROVED: \_\_\_\_\_  
 CHAMBER: O.K. APPROVED: \_\_\_\_\_  
 TEST: No APPROVED: \_\_\_\_\_  
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: \_\_\_\_\_

SEAR-TRIGGER CONNECTOR ENGAGEMENT .010 (MIN. IS .020)

BURRS ON TRIGGER, SMALL BURR ON SEAR.

COMPLAINT: FIRES WHEN SAFETY IS RELEASED.

INCIDENT: FOLLOW DOWN.

COMMENTS: CUSTOMER'S MALFUNCTION NOT DUPLICATED.  
 APPARENTLY THE TRIGGER-SEAR BIND WAS ENOUGH  
 TO PREVENT RETRACTION INTO COCKED POSITION.

PLAINTIFF'S  
EXHIBIT

3192

AL 0029722