

Cust. Complaint

No GUN EXAMINATION REPORT NUMBER: _____

MODEL: 700 BDL

GENERAL CONDITION: NEW

R #: 000219

OUTSIDE WORK: No

DATE: 1-4-72

FIRED AMMO TYPE: _____

FROM: BAY CITY HOW. CO.

BAY CITY, MICH.

& CONDITION: _____

GUN #: 6425267

PROOF: R.F.D.-K

INSP.: _____

72

TEST: 87

CODE: CU = 4/71

HEADING: O.K.

GA./CAL.: 300 W.M.M.S.

BREECH OPENING: -

CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: No

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

No Broken or Damaged Components.

TRIGGER PULL 5 POUNDS, HORIZONTAL ENGAGEMENT .020

(MIN. IS .020) VERTICAL ENGAGEMENT .035 (MIN. IS .015)

TRIGGER DOES NOT RUB ON TRIGGER GUARD.

COMPLAINT: "WHEN SAFETY IS PULLED BACK GUN FIRES WITHOUT
PULLING TRIGGER."

INCIDENT: FOLLOW DOWN.

COMMENTS: CAN FIND NO DEFECT WHICH MIGHT LEAD TO

THE CUSTOMER'S MALFUNCTION. HIS MALFUNCTION
NOT DUPLICATED.PLAINTIFF'S
EXHIBIT

3202

AL 0029732