

M165	, OUT OF SPECS	, RIB DOES NOT ALIGN WITH RECEIVER
M166	, OUT OF SPECS	, RIB IS DAMAGED
M167	, BROKEN PART	, RIB LANDS ARE LOOSE
M168	, OUT OF SPECS	, RIB SWEEPS TO THE LEFT
M169	, OUT OF SPECS	, RIB SWEEPS TO THE RIGHT
M170	, OUT OF SPECS	, SCOPE MOUNT THREADS UPSET IN RECEIVER
M171	, FINISH	, CAMO FINISH WORN/DAMAGED
M172	, FUNCTION	, CLOSURES HARD OVER SHELL
M173	, OUT OF SPECS	, BARREL BRACKET OUT OF POSITION
M174	, OUT OF SPECS	, BOLT STOP STICKS
M175	, MISCELLANEOUS	, ISS BOLT LOCKED IN THE OPEN POSITION
M176	, OUT OF SPECS	, RETURNED FOR RECALL/UPDATE
M177	, OUT OF SPECS	, STOCK NOT BEDDED PROPERLY
M178	, OUT OF SPECS	, TRIG ADJ SCREWS RESET, CANNOT READJUST
M179	, OUT OF SPECS	, BARREL TO RECEIVER MISALIGNMENT
M180	, OUT OF SPECS	, EXTRACTOR HITS INSIDE CHAMBER
M181	, FUNCTION	, BURR AT RIM AREA OF CHAMBER
M182	, FUNCTION	, CARRIER OUT OF ADJUSTMENT
M183	, OUT OF SPECS	, GAS ORIFICE HOLE IS OVERSIZE
M184	, BROKEN PART	, MAGAZINE TUBE SEPARATED FROM RECEIVER
M185	, MISCELLANEOUS	, THREE SHOT PLUG AT WRONG END OF MAG TUBE
M186	, BROKEN PART	, ACTION SPRING TUBE FELL OFF
M187	, BROKEN PART	, BARREL GUIDE STUD MISSING
M188	, BROKEN PART	, BARREL SUPPORT SEPARATED FROM MAG TUBE
M189	, BROKEN PART	, CARRIER LATCH IS BROKEN
M190	, BROKEN PART	, GAS CYLINDER SEPARATED FROM BARREL
M191	, OUT OF SPECS	, GAS HOLES OUT OF POSITION
M192	, BROKEN PART	, MAG LATCH BROKEN / SEPARATED FROM HOUSING
M193	, OUT OF SPECS	, CARRIER LATCH TAB OUT OF ADJUSTMENT
M194	, FUNCTION	, ACTION BAR LOCK CATCHES BETWEEN ACTION BAR AND
RECEIVER		
M195	, MISCELLANEOUS	, ACTION CLOSURES TOO EASILY
M196	, FUNCTION	, ACTUATING ROD BENT/LOOSE
M197	, OUT OF SPECS	, CHOKE TUBE CONCENTRICITY - BOTTOM BARREL
M198	, OUT OF SPECS	, CHOKE TUBE CONCENTRICITY - TOP BARREL
M199	, FUNCTION	, COCKING RODS BIND
M200	, MISCELLANEOUS	, DEBRIS UNDER REAR CONNECTOR
M201	, FUNCTION	, DOUBLES
M202	, FUNCTION	, EJECTOR - BOTTOM BARREL EJECTS TOO SOON
M203	, OUT OF SPECS	, EJECTOR SEAR OUT OF ADJUSTMENT
M204	, OUT OF SPECS	, EJECTOR SEAR TOO LONG
M205	, FUNCTION	, EJECTOR SYSTEM HAS INCORRECT TIMING
M206	, FUNCTION	, EJECTORS BIND
M207	, FUNCTION	, FAILS TO COCK
M208	, FUNCTION	, FIRING PINS BIND IN FRAME
M209	, OUT OF SPECS	, FRAME FACE IS ROUGH/FIRING PIN HOLES RECESSED
M210	, BROKEN PART	, GAS CYL CRACKED
M211	, MISCELLANEOUS	, GUN RECEIVED IN MANUAL SAFETY MODE
M212	, MISCELLANEOUS	, GUN RECEIVED WITH SAFETY LOCKED OFF
M213	, FUNCTION	, HAMMERS DO NOT COCK - NO OVERCOCK
M214	, BROKEN PART	, INTERCEPTOR LATCH STUD MISSING
M215	, FUNCTION	, LOCKING BOLT OVERLOCK
M216	, FUNCTION	, OPENS WHEN FIRED
M217	, OUT OF SPECS	, OVER LOCKED
M218	, OUT OF SPECS	, PREPLAY ON SEAR NOT TO FACTORY SPECIFICATIONS
M219	, MISCELLANEOUS	, CARDBOARD PACKING RING WAS NOT REMOVED
M220	, MISCELLANEOUS	, PISTON/PISTON SEAL INCORRECTLY INSTALLED
M221	, OUT OF SPECS	, RECEIVER FEED CUTS ARE ROUGH
M222	, MISCELLANEOUS	, MODIFY TUBE CAPACITY TO ACCEPT TEN ROUNDS
M223	, BROKEN PART	, ACTION TUBE RING BROKEN
M224	, OUT OF SPECS	, BREECH PLUG FROZEN IN BREECH
M225	, BROKEN PART	, EJECTOR SPRING IS BROKEN
M226	, OUT OF SPECS	, FORE END TUBE NUT IS LOOSE - FORE END RUBS
BARREL		
M227	, BROKEN PART	, GAS BLOCK SEPARATED FROM BARREL