

complete system costs \$6,000.

Rear sight: Detachable Redfield Palma Match open sight provided for emergency usage.	Receiver: Drilled and tapped for scope mount with #8-40 holes, and #6-48 screw holes for receiver sight. Steel trigger guard and floor plate are manufactured by Dakota Arms.
Receiver marking: Remington M700 / M24 and U.S. is stamped on rifles intended for the U.S. Army.	Safety: Ambidextrous two-position safety modified to give equal on-off safety force.
Scope: Leupold-Stevens Ultra M-3A day optic sight, fixed at 10-power, with Mil Dot system range-finding reticle. Has a bullet drop compensator and is adjustable for parallax (focus). The scope caps are commercially available from Butler.	
Serial number location:	Bottom of turret (same as product B.A.C.F.).