

Curt Camp?

No GUN EXAMINATION REPORT NUMBER: MODEL: 700

GENERAL CONDITION: GOOD R #: 023332

OUTSIDE WORK: No DATE: 11-13-72

FIRED AMMO TYPE: - FROM: GRANTS' FOR GUN INC. COSTA MESA, CAL.

& CONDITION: GUN #: 6449597

PROOF: REP-N INSP. 89 TEST: 53 CODE: WV = 8/71

HEADING: O.K. PR./CAL.: 3006

BREACH OPENING: CHECKED BY: C PROSSER

RECOIL SHOULDERS: O.K. APPROVED:

CHAMBER: O.K. APPROVED:

TEST: No APPROVED:

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED:

SEAR-TRIGGER CONNECTOR ENGAGEMENT = 0.010
(MIN. IS .020) BURRS ON SIDES OF TRIGGER

COMPLAINT: GUN FIRES WHEN SAFETY IS TAKEN OFF.

INCIDENT: FOLLOW DOWN

COMMENTS: IT APPEARS THAT TRIGGER BIND MAY HAVE
PREVENTED FULL RETRACTION OF CONNECTOR UNDER
THE SEAR REDUCING THE UNDER MIN. ENGAGEMENT
TO ZERO.PLAINTIFF'S
EXHIBIT

3206

AL 0029736