

	D	E
245	EJECTOR DOES NOT HAVE ENOUGH TENSION	X
246	EJECTOR STUCK IN BOLT	X
247	FREEBORE MISCUT / MIN	X
248	SCOPE MOUNT THREADS UPSET IN RECEIVER	X
249	CAMO FINISH WORN/DAMAGED	X
250	CLOSER HARD OVER SHELL	X
251	BARREL BRACKET OUT OF POSITION	X
252	BOLT STOP STICKS	X
253	ISS BOLT LOCKED IN THE "OPEN" POSITION	X
254	RETURNED FOR RECALL/UPDATE	X
255	STOCK NOT BEDDED PROPERLY	X
256	TRIG ADJ SCREWS RESET, CANNOT READJUST	X
257		
258	MALFUNCTIONS	MODELS 40X 8882
259	ACCURACY	X
260	BALANCE OF FIREARM IS NEEDED TO PERFORM PROPER REPAIR	X
261	BUTT PLATE / RECOIL PAD IS BROKEN	X
262	CHAMBER ROUGH / RINGS / TEARS / TIGHT	X
263	CONSIGNED GUN	X
264	COULD NOT DUPLICATE CUSTOMERS COMPLAINT	X
265	CREDIT RETURN	X
266	DAMAGE APPEARS TO HAVE OCCURRED IN TRANSIT	X
267	DAMAGES CASES, BULLETS OR SHELLS	X
268	FAILS TO FIRE	X
269	FINISH IS DAMAGED ON TRIGGER GUARD/PLATE	X
270	HEADSPACE IS EXCESSIVE	X
271	MUZZLE DAMAGE	X
272	NO CORRESPONDENCE	X
273	NO FAULT FOUND AT BENCH	X
274	PACKING ERROR	X
275	POOR FINISH - BARREL	X
276	POOR FINISH - FORE END	X
277	POOR FINISH - RECEIVER (OR FRAME)	X
278	POOR FINISH - STOCK	X
279	RECEIVER IS MISCUT	X
280	RUSTED COMPONENT	X
281	SAFETY CONCERN, EXAMINED BY PRODUCT SERVICE	X
282	SIGHTS OFF CENTER	X
283	STOCK CRACKED	X
284	STOCK MARRED	X
285	TRIGGER PULL IS OUT OF FACTORY SPECS.	X
286	CHAMBER DIRTY / RUSTY	X
287	FAILS TO EXTRACT	X
288	HEADSPACE AT MINIMUM	X
289	LIGHT OR NO INDENT FROM FIRING PIN	X
290	BLUING SALTS ARE BLEEDING FROM METAL	X
291	EXTRACTOR MISSING	X
292	FAULTY MAGAZINE	X
293	TRIGGER CONNECTOR BINDS	X
294	EXTRACTOR IS BROKEN	X
295	FAILS TO EJECT	X
296	WILL NOT FEED PROPERLY	X
297	RIFLING ROUGH / MISCUT / DAMAGED	X
298	ACTION IS DIFFICULT TO OPEN	X
299	EXTRACTOR IS CATCHING ON SHELL HEAD	X
300	MAGAZINE DIFFICULT TO LOAD	X
301	BOLT HANDLE FELL OFF, BOLT IS BROKEN	X
302	RECEIVER PLUG SCREWS BROKEN	X
303	RECEIVER SCOPE MOUNT HOLES OFF CENTER	X
304	BOLT FACE / SHROUD DAMAGED	X
305	BORE IS HEAT CHECKED	X