	D	E ***
489	BOLT STOP STICKS	X
490	ISS BOLT LOCKED IN THE "OPEN" POSITION	×
491	RETURNED FOR RECALL/UPDATE	×
492	STOCK NOT BEDDED PROPERLY	× 1
493	TRIG ADJ SCREWS RESET, CANNOT READJUST	``X
494		
495	MALFUNCTIONS MODELS	572*****
	ACCURACY	. х
	BALANCE OF FIREARM IS NEEDED TO PERFORM PROPER REPAIR	*****
	BUTT PLATE / RECOIL PAD IS BROKEN	*
	CHAMBER ROUGH / RINGS / TEARS / TIGHT	Xeedille.
	CONSIGNED GUN	X
	COULD NOT DUPLICATE CUSTOMERS COMPLAINT	. X
	CREDIT RETURN  DAMAGE APPEARS TO HAVE OCCURRED IN TRANSIT	******************************
	DAMAGES CASES, BULLETS OR SHELLS	X
	FAILS TO FIRE  FINISH IS DAMAGED ON TRIGGER GUARD/PLATE	X
	HEADSPACE IS EXCESSIVE	≫ x
	MUZZLE DAMAGE	
	NO CORRESPONDENCE	x l
	NO FAULT FOUND AT BENCH	- x
	PACKING ERROR	x
512	POOR FINISH - BARREL	х
513	POOR FINISH - FORE END	×
514	POOR FINISH - RECEIVER (OR FRAME)	X
515	POOR FINISH - STOCK	×
516	RECEIVER IS MISCUT	X
517	RUSTED COMPONENT	X
	SAFETY CONCERN, EXAMINED BY PRODUCT SERVICE	X
	SIGHTS OFF CENTER	X
	STOCK CRACKED	X
***********	STOCK MARRED	X
	TRIGGER PULL IS OUT OF FACTORY SPECS.	×
	FAILS TO EXTRACT	x
	HEADSPACE AT MINIMUM	x
	LIGHT OR NO INDENT FROM FIRING PIN	x l
	EXTRACTOR MISSING	x
	FAULTY MAGAZINE	X
529	TRIGGER CONNECTOR BINDS	x
	EXTRACTOR IS BROKEN	x
531	FAILS TO EJECT	×
	WILL NOT FEED PROPERLY	×
	RIFLING ROUGH / MISCUT / DAMAGED	×
	MAGAZINE DIFFICULT TO LOAD	X
	FORE END CRACKED	X
	FORE END IS TOO TIGHT	X
	FORE END IS TOO LOGSE.	X
	FORE END MARRED GRIP CAP IS DAMAGED	X X
	ACTION BAR IS BROKEN	×
	ACTION BAR LOCK CATCHES BETWEEN ACTION BAR AND RECEIVER	×
	MODIFY TUBE CAPACITY TO ACCEPT 10 ROUNDS	x
	LOCKING BAR ASSEMBLY BROKEN	x l
544		^`
545	₫ 0000000000000000°	· · · · · · · · · · · · · · · · · · ·
	ACCURACY	× × × × × × × × × × × × × × × × × × ×
	BALANCE OF FIREARM IS NEEDED TO PERFORM PROPER REPAIR	x
	BUTT FLATE / RECOIL PAD IS BROKEN	×
549	CHAMBER ROUGH & RINGS / TEARS / TIGHT	х
	000000	