

N/700 Customer Complaint

... N/0 GUN REGISTRATION REPORT NUMBER: _____ MODEL: 700 YARMINT

GENERAL CONDITION: NEW R # : 014704

OUTSIDE WORK: SCORE MOUNTED. DATE: 7-21-72

FIRED 8000 TYPE: - FROM: BILLINGS P.D.

& CONDITION: _____ BILLINGS, MONT.

PROOF: R.E.P. IMPV.: 7.8 TEST: 55 GORE: RP = 1/62

WEADING: _____ GR./DALY: 22-250

BARECH OPENING: - CHECKED BY: C. PROSSER

RECOIL SHOULDERING: O.K. APPROVED: _____

CHAMBER: O.K. APPROVED: _____

TEST: _____ APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER CONNECTOR BROKEN.

COMPLAINT: "GUN FIRES ON LOSING THE BOLT." ALSO REPORTED IN KEYHOLE.

INCIDENT: FALLON DOWN

COMMENTS: THE FALLON DOWN WAS A RESULT OF THE BROKEN TRIGGER CONNECTOR FAILING TO RETRACT.

PLAINTIFF'S
EXHIBIT

3220

10/1
AL 0029752