

- **Model 700/Seven Snaked Firing Pin Spring**  
**OBJECTIVE:** Quality Improvement  
**Action:** Diaz to review status. How can/will this be utilized with removal of ISS?  
**Testing** will be conducted in conjunction with ISS removal at E-Town.  
**ACTION:** Review at next PTM
  
- **Model 597 Performance Improvement**  
**OBJECTIVE:** Performance Improvement of 597  
**Action:** Trull/Diaz to report on site audit findings  
**Action:** Discussion on possible ways to improve/modify box  
Trull/Diaz discussed site findings. Basically confirmed what everyone already knew.  
High degree of user sensitivity, combined with adversity to fouling and issues with  
spring compression. Agreed that there was not a great deal of value in further  
testing, but more value in solving the problem.  
  
Appears that best options are to make the box taller and thinner (I.D.). This would  
improve the performance of the stack, exert less outward pressure and ease loading  
(speculative, not tested yet). Also, follower material change was discussed.  
  
**ACTION:** Diaz to work with Franz and lay out plan by next PTM.
  
- **Remington Mohawk 22 Program**  
**Action:** Trull to provide direction and solicit input.  
Reviewed old Model 514. This concept is precisely what we are looking for.  
**ACTION:** Diaz/Murphy to review M514 & M10. Trull to issue NPP.  
All to report at next PTM.

## **MAYFIELD BASED RIFLE PRODUCTS**

### **2004 New Rifle Product — Mayfield**

- **Model 504**  
**OBJECTIVE:** New Product  
**DAT testing is complete.** E-Town engineers spending a lot of time at Mayfield gearing  
up for T&P run. Production parts are coming in now.
  
- **Model 710 Magnum**  
**OBJECTIVE:** New Product  
**Action:** Mayfield to review status of heat treated barrels and layout build plan.  
Heat treating process appears to be working. T&P run scheduled for October (300  
Pieces of 300 Win Mag). First production scheduled for December.

### **Mayfield Production Topics**

- **Model 597 17 HMR**  
**OBJECTIVE:** Production Update  
Orders are holding fairly well, but we should continue to maintain a cautious view,  
especially with respect to wood issues.  
**Action:** Review production and order position