

Recall on Model 600 Mohawk

Discussion Thread

Response (Laura) 4/21/2001 6:35:58 PM
 At 12/20/2000 04:16 PM we wrote -
 Dear Sir,
 We regret that you experienced a problem with your firearm. A few items to check would be the nipple, this may need to be replaced. The percussion cap could have had a problem. And one of the most important items to check is that the firing pin assembly has been taken apart and cleaned thoroughly. If you have checked these items and the firearm is still having problems, we suggest you send it in for evaluation.

Customer (Richard Arrington) 12/19/2000 3:00:56 AM
 2nd Email

I forwarded the following information your on-line technical staff:

Incident Details:
 Summary: I just bought this Remington Mohawk - 600 .308 and I absolutely love it.
 Now...
 Reference #: 001202-0009
 Topic: History
 Sub-Topic: Firearms--History
 Contact: texaslawdog@hotmail.com
 Date Created: 12/02/2000 05:43 AM
 Last Updated: 12/02/2000 05:43 AM
 Elapsed Time: 0 Minutes
 Status: Unresolved
 Model Number: Mohawk - 600
 Serial Number: 6533223

Description:
 I just bought this Remington Mohawk - 600 .308 and I absolutely love it. Now I am intrigued about it's origin. Stamped in the left side of the berrel are the letters "U A W" and what looks like a 9 and an 8 or 6. Stamped in the right side of the barrel are the letters "R.E.A." inside an oval with the letter "M" on the outside of the oval. Can you tell me the manufacture date of this weapon and some of the history behind it? Is there a specific website I can goto to get this type of information? If so, where? Also, I could would appreciate it very much if you could send me an Owner's Manuel for this rifle.

Please send to: Richard Arrington
 461 Jacoby Lane
 Aransas Pass, Texas 78336

Thank you very much for your time and dedication concerning mine and so many others question. You do a great job and should be commended. I hope you have a great Christmas.

On 12/12/00 I located a website that spoke of a recall of this rifle, what I am wondering is if with the information I have provided you can you tell me if the repair or replacement parts have been installed on my particular rifle?

The following is an excerpt from an articale out of Field and Streams January 1979 Edition: