

around 1976. I heard about the safety news report on CBS television network last week concerning the safety mechanism on these weapons. In addition, I have just reviewed your company's safety message on your web site regarding the safety lock and proper handling procedures. It is my understanding that there is nothing mechanically wrong with the safety mechanism on pre-1982 rifles, but the problem arises from improper handling procedures. Can you confirm that this assertion is correct?

Sincerely,

Oliver H. Warren
956 Monmouth Road
Tuscaloosa, AL 35406
(205) 752-8497