This is in regards to your safety modification program. It have that this gun  $f\dots$ 

Discussion Thread

Response (Laura) 3/8/2002 10:19:02 AM Dear Mr. Genske,

Thank you for your inquiry. Remington Sportsman 78 bolt-action rifles are not included in the safety modification program. These rifles have been manufactured since 1982 and do not have a bolt lock mechanism. As a result these rifles may be loaded or unloaded with the safety in the "5" or "On Safe" position.

Nevertheless, as with any firearm, special care must be taken during the loading and unloading process. Always keep the muzzle pointed in a safe direction. Always unload your rifle when not actually in use. Keep the safety in the "5" or "on Safe " position at all times until you are ready to shoot. Every firearm should be unloaded as soon as you are finished shooting — before taking it into your car carp or house. Remington wants you to enjoy the shooting sports — safely!

Should you desire service on any of your Remington firearms please feel free to call us on our toll free service line (800) 243.9700 or visit the Remington Authorized Repair Center nearest you.

You can find this information on the front page of our website at www.remington.com.

Customer (rick genske)

This is in regards to your safety modification program. I have had this gun for several years,I won is at a banquet and it has never been fired. I am concerned if this gun needs to be repaired. Please let me know.

