

*Custom Complaint*P.I. NO GUN EXAMINATION REPORT NUMBER: _____MODEL: 700 BDLGENERAL CONDITION: GOODR #: 23021OUTSIDE WORK: SCOPE MOUNTED TRIGGERDATE: 11-15-71ADJUSTMENTS CHANGEDFROM: WILLIAM H. ULERYFIRED AMMO TYPE: -OBERLIN, KANSAS& CONDITION: ASSEMBLER 73GUN #: 6456668PROOF: R.E.P. - D INSP. 73 TEST: 66CODE: OU = 7/91HEADING: CLOSES OVER MAX. BELT GAGE.GR./CAL.: 7MMBREACH OPENING: -CHECKED BY: C. PROSSERRECOIL SHOULDERS: EXCESSIVE RADIUS AT REAR.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: NO

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

NO DAMAGED COMPONENTS.COMPLAINT: WENT OFF ACCIDENTALLY WHILE UNLOADING, AGAIN LATER WHILE LOADING.INCIDENT: FOLLOW DOWN.

COMMENTS: CUSTOMER'S MALFUNCTION NOT VERIFIED BY WRITER,
HOWEVER HIS READJUSTING HAS MADE IT IMPOSSIBLE TO
DETERMINE WHETHER THE RIFLE WAS CORRECTLY
ADJUSTED ON FINAL ASSEMBLY.

PLAINTIFF'S
EXHIBIT

3232

AL 0029764 10/10