I recently saw your bolt lock modification program...I think my $700\ was\ made\ \dots$

Discussion Thread

Response (Laura) Dear Mr. Heaton, 4/24/2002 3:07:48 PM

Thank you for your inquiry. To determine whether your Model 700 or 40-X rifle has a bolt-lock mechanism, either:

Call Remington toll-free at (877)387-6691 and a service representative will help you determine if your firearm has a bolt-lock mechanism, or

Take your Model 700 or 40-X rifle to a Remington Authorized Repair Center and a qualified gunsmith will examine your firearm and determine whether it has a bolt-lock mechanism.

We cannot return your firearm to you with a 2.1/21b trigger pull. This is below our factory specifications.

Customer (Lewis Heaton) 4/17/2002 9:42:11 AM
I recently saw your bolt lock modification programs 1 think my 700 was made in 1968, it currently has a trigger pull of 21/4-2 1/2 pounds, which is ideal for a target/varmit gun... first is this rifle affected by the bolt lock program, second, if it is returned, and the trigger group replaced can I still have a 2-3 pound trigger pull, Do you plan on making a rifle for the .17hmr, do you plan on making ammunition for this calibre. And please make more 5mm magnum ammunition. I only have 300 rounds left.....thank you..Louie Heaton

