I have a Remingtom Model 700 ADL 30-06 that once discharged when I simply ${\sf cha...}$

Discussion Thread

Response (Laura) 10/16/2002 11:26:33 AM
Dear Mr. Smith,
Based on your notation that the firearm discharged, we strongly recommend that you send it to us for evaluation.

Customer (Art Smith) 10/3/2002 7:11:03 PM > The serial # on my rifle is: 247542. I'm relatively sure that it was manufactured prior to 1982, as I purchased it used in 1983 or 1984. If this firearm qualifies for the Safety Modification program, please let me know and I will send it in. Thank You,

>

Art Smith