

P NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 660GENERAL CONDITION: NEW R #: 006930OUTSIDE WORK: SCOPE MOUNTED, SWIVELS ADDED DATE: 3-13-72CEMENT REMOVED - REAR ADJUSTING SCREW FROM: ACKERMAN'S FIRST
AND SUPPLIESFIRED AMMO TYPE: - GROVE CITY, PA.& CONDITION: _____ GUN #: 111373PROOF: R.I.D. ASPECTS INSP.: 73 TEST: 79 CODE: KR = 5/68HEADING: - GA./CAL.: 223 W.M.BREACH OPENING: - CHECKED BY: PROSSERRECOIL SHOULDERS: O.K. APPROVED: _____CHAMBER: O.K. APPROVED: _____TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR AND TOP INSIDE OF HOUSING COATED WITH DRIED
LUBRICANT OR OTHER MATERIAL.COMPLAINT: "GOES OFF WITHOUT WARNING."INCIDENT: FOLLOW DOWNCOMMENTS: THE LUBRICANT OR WHATEVER, SHOULD INFLUENCE
RESPONSE OF TRIGGER ASSEMBLY - TRIGGER FULLY TO
RESET - SEAR FALLS TO RESET TO COCKED POSITION.PLAINTIFF'S
EXHIBIT

3238

- 1 of 1
AL 0029770