

I have submitted a previous question two or three weeks ago, and have yet to ...

Discussion Thread

Response (Chris)

8/5/2003 4:46:11 PM

Dear Mr. Williams,

We apologize for the delay. Your Model 700 was produced in 1968. Your firearm has not been involved in a recall. We suggest taking or sending your firearm to a Remington Authorized Repair Center or our factory for evaluation.

You can locate your nearest repair center by visiting the Repair Information Center in our Support Section and selecting your model and state:

<http://www.remington.com/repairsvc/Modelselection.asp>

Your rifle was originally installed with a bolt-lock, which means you have to put the safety switch on fire before you can open the bolt. We are offering a conversion at a special price if you would like your firearm converted, so that you can open the bolt at anytime with the safety on safe. To view more details regarding this modification, go to:

http://www.remington.com/Safety_Modification_Program/remington_safety.htm

Customer (Steve Williams)

8/3/2003 8:54:53 PM

I have submitted a previous question two or three weeks ago, and have yet to receive a response. Let me know if I need to resubmit it. The question pertained to a recall of this model to correct a problem with inadvertent firing when the bolt is closed.