

Age

Discussion Thread

Response (Denis)

8/21/2003 2:50:05 PM

Dear Martin:

Thank you for your inquiry. The Model 700 that you have was manufactured in 2001 at our firearms plant in Iliou New York. Your firearm is not subject to the Bolt Lock safety Modification Program. This program applies to firearms that were manufactured prior to 1982 that were manufactured with the bolt lock on the safety. We do not have restrictions on the use of "factory loads" that were manufactured in the United States. We do not recommend ANY military surplus ammunition. We do not recommend the use of ammunition that is manufactured outside of this country. Our rifles are designed to withstand factory ammunition that is loaded in accordance to SAMMI specifications. We hope that this information is helpful to you. If you have further questions feel free to contact us.

Customer (Martin Beyer)

8/14/2003 10:19:19 PM

Sorry, meant to include serial number -- 06601520. Thanks, M. Beyer