

Recall for new trigger group

Discussion Thread

Response (Chris)
Dear Mr. Atkison,

8/22/2003 8:06:44 AM

Thank you for contacting Remington Country. Your Model 600 was produced in 1975 and should be inspected for a trigger recall. We suggest taking or sending your firearm to a Remington Authorized Repair Center or our factory for evaluation.

You can locate your nearest repair center by visiting the Repair Information Center in our Support Section and selecting your model and state:

<http://www.remington.com/repairsvc/Modelselection.asp>

To view more information on this safety message, go to:

http://www.remington.com/Safety_Modification_Program/remington_safety.htm

Customer (Randy Adkison)

8/21/2003 7:39:23 PM

I found info stating a recall for this gun had been issued some years ago. This particular firearm demonstrates the exact characteristics described in the recall. Where can I send this gun to for repair.

Thanks