

Phone: 810-653-2131
Fax: 810-658-2140

You can find additional Remington Warranty Centers for the US and internationally at the following section of our site.

<http://www.remington.com/repairsvc/modelselection.asp>

To view the warranty for Remington firearms, go to:

<http://www.remington.com/support/warranty.htm>

Customer (David Vaughan)

11/6/2003 9:32:49 PM

Some time ago there was a safety program for older rifles whose safety locked the bolt so the firearm could not be unloaded. I have 2 older rifles, a Model 722 and a 40X with triggers like this. The program involved sending the rifles to you where they would be inspected and a new safety added that allows the bolt to be opened, or the trigger would be replaced.

Is this still available?

The 722 is really a hazard since, if the safety is not engaged 100% and the trigger is pulled, the gun won't fire, but the firing pin releases against the safety. So, when the safety is switched off, the gun fires! And there is no way to stop this from happening since the bolt cannot be opened to remove the cartridge from the chamber.