

Phone: 270-442-3242  
Fax: 270-442-5022

Send to Williams Gun Sight if you live in the following states: MI, NY,  
CT, RI, NJ, MA, ME  
Williams Gun Sight & Outfitters  
7389 Lapeer Rd., Route #1  
P.O. Box 329  
Davidson, MI 48423  
Phone: 810-653-2131  
Fax: 810-658-2140

You can find additional Remington Warranty Centers for the US and  
internationally at the following section of our site.

<http://www.remington.com/repairsvc/modelselection.asp>

To view the warranty for Remington firearms, go to:

<http://www.remington.com/support/warranty.htm>

Customer (Mark Lynch) 12/3/2003 11:04:16 PM  
I know that you do not provide support for adjusting the trigger, but can  
you at least tell me why the screw on the side with the single screw (Sear  
engagement) would not adjust at all - I could not turn it.

The adjustment that I made are working fine, 1.5# pull, no trigger slop,  
and even the drop test does not cause firing.

Thanks,  
Mark Lynch