model 600 remington rifle

Discussion Thread

Response (Dell) 3/31/2004 9:11:21 AM

Dear Kenny:
Based on the information you have provided, we suggest that you send your firearm to our Ilion, NY facility for the recall work to be taken care of.

For U.S. repairs, please follow these guidelines:

- Record the serial number of your firearm pefore serial is to us.
- 2. Pack your firearm for safety and to prevent damage in shipping and handling. Preferably, ship in a firearm box, not a hardcase.
- Remove all accessories from your firearm to prevent loss or damage.This would include scope, slings, or extra choke tubes.
- 4. Enclose a letter with the firearm detailing the model name or number of your firearm and serial number along with a letter stating that you are sending it in for the 1979 recall on Model 600 and 660 rifles. Be sure to include your full name and address (F.O. Box and Sireet Address), including zip code, daytime telephone number, and e-mail address.
- 5. Ship your firearm by either United Parcel Service (UPS) or Parcel Post (US Post Office). Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier. Customer is responsible for shipping charges to the factory.

For U.S. repairs only, ship to:

Remington Arms Company, Inc.
Attn: Arms Services Division/Repairs
14 Hoefler Avenue
Ilion, NY 13357

WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.

If you have any questions as to the warranty on Remington firearms, please refer to our Firearms Warranty .

Customer (kenny kolojaco). 3/10/2004 8:46:32 PM I have a remington 243 model 600 mohawk.I heard there was a recall on this gun due to the safety mechanism. I never received any info on this from remington and the original owner.How do I get this fixed under the recall.

