

NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
 GENERAL CONDITION: GOOD R #: 005424
 OUTSIDE WORK: TRIGGER STOP SCREEN SEAL DATE: 2-25-72
 FROM: DONALD GABNON
 FIRED AMMO TYPE: _____ CHICAGO, ILLINOIS
 & CONDITION: _____ GUN #: 6362419
 ASSEMBLER V
 PROOF: R.E.P.-A INSP.: 58 TEST: 13 CODE: DT-9/70
 HEADING: _____ GR./CAL.: 300 G SPR.
 BREACH OPENING: - CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: _____ APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO DAMAGED COMPONENTS. HORIZONTAL ENGAGEMENT

.030 MIN. = .020 CONNECTOR CLEARANCE ON TRIGGER =

1.072 MID = ^{1.079} 1.076 TRIGGER CLEARANCE ON CONNECTOR =

1.089 MID = ^{1.083} 1.080. TRIGGER STOP SCREEN SEAL BROKEN.

TRIGGER BIND DETECTABLE, LUBRICANT TOO HEAVY.

COMPLAINT: FIRES WHEN SAFETY IS RELEASED.

INCIDENT: TRIGGER FAILS TO RETRACT.

COMMENTS: THE FIT OF THE TRIGGER TO THE HOUSING, TOO
 HEAVY LUBRICANT & EXCESS CLEARANCE BETWEEN
 CONNECTOR AND TRIGGER (.010) COULD LEAD TO THE
 CUSTOMER'S MALFUNCTION.

PLAINTIFF'S
EXHIBIT

3241

1 of 1
AL 0029773