

> >
> > Subject
> > -----
> > light marks on my 700 bdl barrel
> >
> >
> > Discussion Thread
> > -----
> > Response (Chris) - 09/27/2004 11:05 AM
> > Dear Mr. Alam,
> >
> > You will see your accuracy drop as the barrel heats up. You should
allow
> > the barrel to cool before continuing to shoot. The amount of shots it
takes
> > to heat it up depends on the caliber, velocity and the barrel thickness.
> > After about 10 shots you should let it cool before continuing to prevent
> > premature wear.
> >
> > Customer (shiraz alam) - 09/25/2004 10:28 AM
> > >
> > > Dear Chris
> > >
> > > I was at bass pro shop a while ago. I was inquiring about my rifle.
They
> > > told me not to fire more than 4 rounds at one time, the reason they
> > > gave
> > > me
> > > was --- that there is a lot of velocity and power in 30.06 bullet and
it
> > > can
> > > ruin the barrel on repeated fire as the barrel get hot. but i had
heard
> > > from
> > > my gun smith that we can even fir 40-50 rounds at one time with these
> > > rifles, since they are of such high quality. pls guide me on this????
> > >
> > > regards
> > >
> > > alam
> > > >
> >
> > Customer (shiraz alam) - 09/25/2004 02:26 AM
> > >
> > > Dear Chris
> > >
> > > I was at bass pro shop a while ago. I was inquiring about my rifle.
They
> > > told me not to fire more than 4 rounds at one time, the reason they
gave
> > > me
> > > was --- that there is a lot of velocity and power in 30.06 bullet and
it
> > > can
> > > ruin the barrel on repeated fire as the barrel get hot. but i had heard
> > > from
> > > my gun smith that we can even fir 40-50 rounds at one time with these
> > > rifles, since they are of such high quality. pls guide me on this????
> > >
> > > regards
> > >
> > > alam
> > > >
> >
> >