

Model 600

Discussion Thread

Response (Chris)

2/7/2005 3:46:03 PM

Dear Mr. Holmes,

Thank you for your inquiry. By the serial number, your XP100 was produced around 1982. It has not been involved in a recall and does not have the bolt lock.

Customer (Jim Holmes)

2/2/2005 3:37:56 PM

> Thank you for the response. As this rifle is in another state with my  
> grandson right now, I will not be able to followup on serial number at  
> this time. We will find an authorized Remington repair site as  
instructed  
> and go further. Thank you again. Incidentally, I still need to know if  
> the XP100 is subject to this problem. My XP is the 7MM BR version,  
serial  
> number B7517725. Thanks for any help you can offer.  
Jim Holmes  
>