old Mohawk 600 recall question

Discussion Thread

Response (Chris) Dear Gordon, 2/15/2005 12:49:56 例

Thank you for your inquiry. This rifle was produced in 1976 and was not included in the recall.

Your rifle was originally installed with a bolt-lock, which means you have to put the safety switch on fire before you can open the bolt. We are offering a conversion at a special price if you would like your firearm converted, so that you can open the bolt at anytime with the safety on safe. To view more details regarding this modification, go to:

http://www.remington.com/Safety_Modification_Program/remington_safety.htm

Customer (Gordon Loucks) 2/14/2005 2:15:30 PM I have a model Mohawk 600, .243Win, SN #6340360. I bought it used from someone who had no idea regarding the recall for this model, so...

I need to know if this rifle has been "fixed" per the old recall or not.

My hope is that you can tell by the Serial Number. If not, I suppose would have to take it to a knowledgeable repair place to have it looked at. That will mean spending money, so I hope that the records show that this rifle was already attended to many moons ago.

Thx.

--gordon

