

Safety operation?

Discussion Thread

Response (Jonsie)

3/16/2005 8:42:33 AM

Dear Geoff:

We regret you are experiencing a problem with your Model 7001. We would like to speak to you in more detail regarding your inquiry. If you will please contact our Parts & Repair Department with your SERIAL NUMBER, at 1-800-243-9700 Mon-Fri 9-5 EST, our representatives can assist you with this matter.

We are excited to announce the addition of our on-line Country Store! Please click on the link below to see the great products that we have available. We appreciate your loyal support of Remington products and your visit to Remington Country.

<http://www.remington.com/store/default.asp>

Customer (Geoff Gregory)

3/15/2005 2:12:10 PM

I have just purchased a new .270 WIN Model 700 BDL with scopes from Bass Pro Shops, which is a beautiful gun. I am curious: Is the safety lever on the right side of the stock in the F position, supposed to 'easily' move rearwards to the S position. It moves to the S position after you have pulled back the bolt, but it does not seem as though it wants to move to the S position otherwise. It is just something I am curious about. The gun has not been loaded or fired yet. (As I am trying to find my way around it & want to be sure that everything is ok)