

Safety issue bolt-lock mechanism

Discussion Thread

Response (Chris)

11/1/2005 1:32:15 PM

Dear Mr. Cherry,

Thank you for your patience. Your Model 700 was produced in 1969. Your firearm has not been involved in a recall. Your firearm has not been involved in a recall. Your rifle was originally installed with a bolt-lock, which means you have to put the safety switch on fire before you can open the bolt. We are offering a conversion at a special price if you would like your firearm converted, so that you can open the bolt at anytime with the safety on safe.

You can locate your nearest repair center by visiting the Repair Information Center in our Support Section and selecting your model and state:

<http://www.remington.com/repairsvc/Modelselection.asp>

Customer (Arthur Cherry)

10/30/2005 5:42:31 PM

I own a Remington model 700 BDL in 30-06 purchased in the early 70's or late 60's. I bought this rifle new from Woolco in Akron, Ohio while I was in high school. Now I live in Minnesota and saw a recall notice for a bolt-lock mechanism safety issue on the bulletin board at Gander Mountain in St. Cloud, MN the other day.

So, is my particular firearm affected with this safety issue? The serial # on this firearm is: 6291964. Email me back if I need to get it factory serviced or what I need to do. I am hoping that if it needs safety servicing that I will be able to take it in to a gunsmith/retailer around the St. Cloud or Little Falls area.

Thank you.

Arthur W. Cherry
212 8th St. SE
Little Falls, MN 56345

Home phone: 320-632-6607