REMINGTON 700 SAFETY OPERATION

Discussion Thread

Response (Inez) 2/1/2006 12:02:52 RM

Dear David

Please click on the link below for the information you have requested. We hope this information is helpful and we appreciate your loyal support of

http://www.remington.com/safety/safety_center/safety_modification_program/

Customer (DAVID GRAGG) 1/28/2006 12:52:15 PM
I HAVE AN OLDER MODEL 700. THE SAFETY MUST BE IN THE FIRE POSITION FOR THE
BOLT TO OPERATE. CAN THE TRIGGER AND SAFETY BE REPLACED WITH THE NEWER
MODEL? WOULD THE BOLT HAVE TO BE REPLACED ALSO?

