

M/700 Customer Complaint

NO GUN EXAMINATION REPORT NUMBER: MODEL: 700

GENERAL CONDITION: GOOD R #: 19055

OUTSIDE WORK: SEAL MISSING ON TRIGGER ADJ. DATE: 9-26-71

ADJUSTING SCREW. FROM: ALLEN L. WOOD

FIRED AMMO TYPE: + CLINTON, MO.

& CONDITION: GUN #: 6291404

PROOF: R.E.P.-E INSP.: D TEST: 13 CODE: RS-"/69

HEADING: O.K. GA./CAL.: 3006

BREECH OPENING: - CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K. APPROVED:

CHAMBER: O.K. APPROVED:

TEST: NO APPROVED:

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED:

NO BROKEN OR DAMAGED COMPONENTS. STOCK MISSING.

COMPLAINT: FIRES WHEN SAFETY IS PUSHED OFF

INCIDENT: FOLLOW DOWN

COMMENTS: ENGAGEMENT O.K., TRIGGER PULL 5 1/2 LBS. SEAL
MISSING AND ADJUSTING SCREW, FRONT, BACKED OUT 50.
NO TENSION REMAINED TO RETRACT THE TRIGGER.

PLAINTIFF'S
EXHIBIT

3251

AL 0029783