

Cust. Complaint

R 342-1 Rev. 2-15-61

P.I. NO GUN EXAMINATION REPORT NUMBER: 700 ADL

GENERAL CONDITION: GOOD R #: 27191

OUTSIDE WORK: SCOPE MOUNTED DATE: 12-27-71

FIRED AMMO TYPE: H FROM: PECO'S SHOT GUNS,
PECCAR, TEXAS

& CONDITION: ALL GOOD GUN #: 632 3773

PROOF: PERF. INSP.: 72 TEST: 97 CODE: RT = "1"

HEADING: S.E. GA./CAL.: 250G 20mm

BRECH OPENING: - CHECKED BY: C.P.S. - 12-27-71

RECOIL SHOULDERS: O.K. APPROVED:

CHAMBER: O.K. APPROVED:

TEST: 110 APPROVED:

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED:

SEPARATE CONSTRUCTION ENFORCED. 030 CALIBER BULLETS

POUNDS, STOCK ETC. NOT INCLUDED. MARK ON TRIGGER

SIDE INDICATES POSSIBLY BUILT ON TRIGGER GUARD.

NO STOCK MOUNTED OR NO OTHER ATTACHMENT

SPRING.

COMPLAINT: DISCHARGED WHEN SAFETY WAS MOVED FROM SAFE

TO FIRE POSITION.

INCIDENT: FOLLOW DOWN.

PLAINTIFF'S
EXHIBIT

3255

COMMENTS: THE CUSTOMER'S MALFUNCTION WAS NOT DUPLICATED

HOWEVER IT MAY HAVE BEEN CAUSED BY TRIGGER RETURN

IN THE TRIGGER GUARD.

1 of 1

AL 0029787