How is the Model 700 Superior to the Ruger M77?

- M77 Mauser style extractor results in removal of bolt shroud. (See Picture 6)
- M77 receiver mounted ejector results in removal of more of the bolt face. (See Picture 6)
- M77 has no counter bored breech. (See Picture 7)
- All result in lack of case support in M77 vs. M700, i.e. NO THREE RINGS OF STEEL (See Picture 7)

