

7) Cleaning and Maintenance	24	
• To remove the bolt assembly and clean:		25
• To clean the barrel:		25
• To clean receiver and trigger assembly:		26
• To clean the magazine assembly:		26
• To clean the stock:		27
• To clean barrel assembly:		27
• Cleaning Frequency		27
8) Owner's Manual	27	
9) Schematic	27	
10) RAMAC numbers	28	
11) Ballistic / rifle	28	
• Recommended game codes:		28
• Ballistic Chart:		28
• Authorized Repair Centers		28
• Wal-Mart Repair Centers		28

## **HISTORY**

### **SYNOPSIS OF FIREARM HISTORY**

- Originally cataloged in 2001
- Press Release
- Initially introduced in .30-06 with a Bushnell Sharpshooter 3-9x40 scope; clean barrel
  - Bushnell 3-9x40 Matte sharpshooter rifle scope
  - 1. Fully waterproof and fogproof
  - 2. Fully coated lenses
  - 3. Multi-X reticle
  - 4. Fully effective aperture
  - 5. 1 click = 1/4" at 100 yds.
  - 6. 3" eye relief
  - 7. Neoprene eye guard
  - 8. Sure-grip power change ring

Approximately 4/01 – changes made to the scope are as follows:

1. Objective adjustment – reshaped; longer and bigger and easier to turn
  2. Eye piece bigger in diameter
  3. 1/8" longer
- .270 was cataloged in 2001
  - Manufactured only in the Mayfield KY plant; no repairs or parts through our Ilion plant as of 4/01
  - January 2001 production of .30-06 with a Bushnell Sharpshooter 3-9x40 scope was subject to an upgrade. Dealers were notified by phone by current CSR's regarding the update. The upgrade was voluntary and